Service Bulletin

LifeFitness

SB No.GN04061401N

Original Date	Revision Date	Distribution	STATUS	Author
June 14, 2004	N/A	Domestic and International	NEW	R. Herr

Subject: No Power At The Console
Serial Number: N/A

Time Required: ☐15 min ☒30 min ☐45 min ☐1 hr +

Distribute To: ☒Internal ☒Dealer ☒ISO ☐Customer

DESCRIPTION:
The console has No power.

SOLUTION:
Service Test Kit GK61-00002-0052 is available for testing self-powered Cross-Trainers and Bikes without the need to have the console plugged into the unit. The photo below points out what the Service Test Kit consists of.


3-Pin Connector, which plugs into the Polar Connector
LED
6 Volt Battery
16-Pin Connector
Plugs into Network Jack on console